



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION 4  
ATLANTA FEDERAL CENTER  
61 FORSYTH STREET  
ATLANTA, GEORGIA 30303-8960

4WD-RPB

JUN 12 2001

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Mr. Don Williams, Plant Environmental Coordinator  
Grenada Manufacturing, LLC  
635 Highway 332  
Grenada, Mississippi 38901

SUBJ: Comments on RCRA Facility Investigation (RFI) Report  
Grenada Manufacturing, LLC  
EPA ID No. MSD 007 037 278

Dear Mr. Williams:

The Environmental Protection Agency's (EPA) South Programs Section in the RCRA Programs Branch at Region 4 has reviewed the RFI Report at the Grenada Manufacturing Plant in Grenada, Mississippi, dated January 2001. This was the second draft of the document: comments made by EPA on the first draft were addressed. EPA has a few comments before the report is finalized.

After addressing the enclosed comments, please furnish final title pages and replacement pages for all outstanding volumes. Also, please furnish an electronic copy of the document on compact disc. Most common electronic formats and media are acceptable (ex. WordPerfect, Word, Adobe Acrobat).

If you have any questions or concerns regarding this letter, please contact Mr. Don Webster, your EPA Project Manager, at (404) 563-8469.

Sincerely

Narindar M. Kumar  
Chief, RCRA Programs Branch  
Waste Management Division

Enclosures

cc: Louis Crawford, MDEQ;  
John Devic, Textron Automotive;  
John Bozick, Meritor Automotive

Docket Number 451144

EPA Comments on Grenada Manufacturing RFI Report dated January 2001

1. The Reference to Figure 4 on page 2-2 is incorrect. The reference should cite a figure which depicts the Geoprobe locations.
2. Please add a summary of soils data for SWMU 12, page 1. In EPA's opinion, this SWMU may need further investigation of soils for Chromium contamination.
3. Please add to the summary of SWMU 13 that, upon cessation of wastewater treatment operations at the plant, SWMU 13 may need to be closed as a HSWA regulated unit.
4. To the summary of SWMU 14, last line on page one please add "and afterwards, to monitor the effectiveness of the remedial system."
5. The summary of SWMU 15 should consider the investigation of the impact of volatile components of the plume on indoor air, since the plumes of toluene and TCE are both found under the Main Plant Building.

U.S. Postal Service  
CERTIFIED MAIL RECEIPT  
(Restrictable; No Insurance Coverage Provided)

DON WILLIAMS PLANT ENV COORDINATOR  
GRENADA MANUFACTURING LLC  
635 HIGHWAY 332  
GRENADA MS 38901

7099 3400 0000 781A 9371

Return Receipt  
(Endorsement Required)  
Restricted Delivery Fee  
(Endorsement Required)

Total Postage & Fees \$

Name (Please Print Clearly) (to be completed by addressee)

Street, Apt. No.; or PO Box No.

City, State, ZIP+4

PS Form 3800, July 1999

Postmark  
Here

2001

SENDER COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece.

MR DON WILLIAMS PLANT ENVIR COOR  
GRENADA MANUFACTURING LLC  
635 HIGHWAY 332  
GRENADA MS 38901

COMPLETE THIS SECTION ON DELIVERY

A. Received by (Please Print Clearly) B. Date of Delivery

5-31-00

C. Signature

x *Don Williams* (NR)

☐ Agent  
☐ Addressee

Is this mail different from item 1? ☐ Yes  
address below: ☐ No

3. Service Type

- ☒ Certified Mail ☐ Express Mail
- ☐ Registered ☐ Return Receipt for Merchandise
- ☐ Insured Mail ☐ C.O.D.

4. Restricted Delivery? (Extra Fee) ☐ Yes

2. Article Number (Copy from service label)

21 55 056 272

PS Form 3811, July 1999

Domestic Return Receipt

102595-99-M-1789



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 4  
ATLANTA FEDERAL CENTER  
61 FORSYTH STREET  
ATLANTA, GEORGIA 30303-8960

4WD-RPB

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

JUN 12 2001

Mr. Don Williams, Plant Environmental Coordinator  
Grenada Manufacturing, LLC  
635 Highway 332  
Grenada, Mississippi 38901

SUBJ: Comments on RCRA Facility Investigation (RFI) Report  
Grenada Manufacturing, LLC  
EPA ID No. MSD 007 037 278

Dear Mr. Williams:

The Environmental Protection Agency's (EPA) South Programs Section in the RCRA Programs Branch at Region 4 has reviewed the RFI Report at the Grenada Manufacturing Plant in Grenada, Mississippi, dated January 2001. This was the second draft of the document: comments made by EPA on the first draft were addressed. EPA has a few comments before the report is finalized.

After addressing the enclosed comments, please furnish final title pages and replacement pages for all outstanding volumes. Also, please furnish an electronic copy of the document on compact disc. Most common electronic formats and media are acceptable (ex. WordPerfect, Word, Adobe Acrobat).

If you have any questions or concerns regarding this letter, please contact Mr. Don Webster, your EPA Project Manager, at (404) 563-8469.

Sincerely

Narindar M. Kumar  
Chief, RCRA Programs Branch  
Waste Management Division

Enclosures

cc: Louis Crawford, MDEQ;  
John Devic, Textron Automotive;  
John Bozick, Meritor Automotive

DW?1f06/08/01 WEBSTER MCCURRY KUMAR

Internet Address (URL) • <http://www.epa.gov>

EPA Comments on Grenada Manufacturing RFI Report dated January 2001

1. The Reference to Figure 4 on page 2-2 is incorrect. The reference should cite a figure which depicts the Geoprobe locations.
2. Please add a summary of soils data for SWMU 12, page 1. In EPA's opinion, this SWMU may need further investigation of soils for Chromium contamination.
3. Please add to the summary of SWMU 13 that, upon cessation of wastewater treatment operations at the plant, SWMU 13 may need to be closed as a HSWA regulated unit.
4. To the summary of SWMU 14, last line on page one; please add "and afterwards, to monitor the effectiveness of the remedial system."
5. The summary of SWMU 15 should consider the investigation of the impact of volatile components of the plume on indoor air, since the plumes of toluene and TCE are both found under the Main Plant Building